

Kernel

make-command

- <https://github.com/BPI-SINOVOIP/BPI-R64-bsp>
- 4.19 / 5.4-rc
 - both switches working, currently no dsa-driver available
 - bluetooth untested (was working in 4.19)
 - no wifi driver available

debug

```
dev_info(gsw->dev,"%s:%d 0x%x",__FUNCTION__,__LINE__,val);  
printk(KERN_ALERT "DEBUG: Passed %s %d \n",__FUNCTION__,__LINE__);
```

```
#define onelinedbg(dev,fmt,...) {if (dev) dev_info(dev,"%s:%d "  
fmt,__FUNCTION__,__LINE__,##__VA_ARGS__);else printk(KERN_INFO "%s:%d "  
fmt,__FUNCTION__,__LINE__,##__VA_ARGS__);}
```

makefile:

```
$(info $$var is [${var}])
```

From:

<https://wiki.fw-web.de/> - **FW-WEB Wiki**

Permanent link:

<https://wiki.fw-web.de/doku.php?id=en:bpi-r64:kernel>

Last update: **2023/06/08 17:06**

